



For all VW/AUDI/MB/BMW/PORCHE, please use OBD connector, and turn on the key, the make mileage corrections. The following is special attentions for some cars.


A8 03-04:If you can read correct mileage but cannot write it, please remove the fuse for the cluster, wait for about 5 minutes then put the fuse back and repeat the mileage correction procedure.




A8 05-06: If you can read the correct mileage but cannot write in, please remove the fuse for the cluster and wait about 10 minutes then put the fuse back and repeat the mileage correction procedure. If the programmer tells you **“written successful”** but the odometer shows 0 km/mls, please remove the fuse for the cluster and wait about 10 minutes, then reinstall the fuse. The odometer will then show new mileage. For some A8 05-06 models you can also try the **“A8 03-04”** program to correct the mileage.



A6 04-up and Q7: If you select a wrong model when programming, such as you are programming an A6 2004, but you select the “**A6 06.07-up**” program, and after writing the new mileage, the odometer shows 999999 km/mls. Do not worry, remove the fuse for the cluster and wait about 5 minutes, reinstall the fuse and the odometer will show the original mileage. Repeat the programming, but choose the correct model this time.






TOUAREG: Before you write the new mileage you should confirm that the programmer has read the correct mileage. If the programmer cannot read the correct mileage please try another model and read again.

Do not write the mileage if the mileage read is incorrect otherwise there will be a problem after writing.

VW 07-up / Skoda 07-up: For some models the software will tell you to “**turn off the ignition and turn on again**”. If after you turn off and turn on the ignition the cluster does not light up, please remove the fuse for the cluster and wait for 5 minutes. Then reinstall the fuse to illuminate the cluster. Repeat mileage correction procedure.


Attentions: with VW 07-up / Skoda 07-up, tool sometimes can not read current mileage correctly, not worry, this has no influence on programming new mileage in.

VW V1




left of engine compartment

VW V2




left of engine compartment

SKODA OCTAVIA



Front left dash panel

W211\W203: it will not read current mileage, only input new mileage and write. After you put the odometer back to the car ,the instrument cluster will flash for a while , Do not worry, please wait about 2-3 minutes, then it will come back to normal.



BMW 3, 5 SERIES CAS2/CAS3: Remove dashboard first then connect the usa prog to cluster cable as the following picture shows. Then select cas2 or cas3, the usa prog will shows the current mileage, confirm the mileage and input new mileage, then press ok.



BMW 7 SERIES CAS2: Remove dashboard first then connect the usa prog to cluster cable as the following picture shows. Then select cas2, the usa prog will shows the current mileage, confirm the mileage and input new mileage, then press ok.

